



CERTIFICATE



This is to certify that



Gelenkwellenfabrik Wilhelm Sass KG

Brookstraße 14
22145 Stapelfeld
Germany

has implemented and maintains a **Quality Management System**.

Scope:

Manufacturing, repairation and distribution of cardan shafts, their components and connection systems. Development of component parts for cardan shafts and their connection systems

Through an audit, documented in a report, it was verified that the management system fulfills the requirements of the following standard:

ISO 9001 : 2015

Certificate registration no.	380447 QM15
Valid from	2018-07-08
Valid until	2021-07-07
Date of certification	2018-07-08



DQS GmbH

Stefan Heinloth
Managing Director



CERTIFICATE

This is to certify that



Gelenkwellenfabrik Wilhelm Sass KG

Brookstraße 14
22145 Stapelfeld
Germany

has implemented and maintains a **Quality Management System**.

Scope:

Manufacturing, repairation and distribution of cardan shafts, their components and connection systems. Development of component parts for cardan shafts and their connection systems

Through an audit, documented in a report, it was verified that the management system fulfills the requirements of the following standard:

ISO 9001 : 2015

Certificate registration no.	380447 QM15
Valid from	2018-07-08
Valid until	2021-07-07
Date of certification	2018-07-08



DQS GmbH

Stefan Heinloth
Managing Director